

Milling - Geared - Right Angle (RA)

Spindle Type	Product Type	Spindle Model #	Max Speed (rpm)	Tool System	Bearings (mm)	Speed Range A (HP/100 rpm)	Power @ Speed Range A (HP/100 rpm)	Speed Range B (HP/100 rpm)	Power @ Speed Range B (HP/100 rpm)	Speed Range C (HP/100 rpm)	Power @ Speed Range C (HP/100)	Speed Range D (HP/100 rpm)	Power @ Speed Range D (HP/100 rpm)	Weight (lbs)
1RA	Milling - Geared		3000	#30 Taper	50/40	0-1250	2.01	1250-1900	1.84	1900-2550	1.75	2550-3000	1.67	90
2RA			2500	#40 Taper	60/50	0-1090	3.11	1090-1635	2.86	1635-2180	2.71	2180-2500	2.58	175
3RA			2100	#50 Taper	80/70	0-954	4.82	954-1430	4.43	1430-1908	4.19	1908-2100	4.00	350
4RA			1700		90/80	0-763	8.50	763-1145	7.82	1145-1526	7.40	1526-1700	7.06	450
5RA			1500		100/85	0-636	12.60	636-954	11.59	954-1272	10.96	1272-1500	10.46	600
6RA			1300		110/95	0-545	18.70	545-818	17.20	818-1090	16.27	1090-1300	15.52	800
7RA			1200		120/100	0-477	23.00	477-716	21.20	716-954	20.00	954-1200	19.09	1000
8RA			950		130/110	0-382	40.20	382-572	36.98	572-763	34.97	763-950	33.40	1600